

# Peripheral iPod Application Guide

10/23/2007

Make	Model	Year	Part #	Harness	Dip Switch Settings**	Vehicle Specific Notes
Acura	CL	1998-2002	PXDP	PXHHD1	1,4,8 ON	
	CL	1996-1997	PXDP	PXHCH2	1,4,8 ON	
	Integra	1998-2001	PXDP	PXHHD1	1,4,8 ON	
	Integra	1992-1997	PXDP	PXHCH2	1,4,8 ON	
	Legend	1992-1995	PXDP	PXHCH2	1,4,8 ON	
	RL	1998-2002	PXDP	PXHHD1	1,4,8 ON	
	RL	1996-1997	PXDP	PXHCH2	1,4,8 ON	
	RSX	2002	PXDP	PXHHD1	1,4,8 ON	
	TL	1999-2002	PXDP	PXHHD1	1,4,8 ON	
	TL	1996-1997	PXDP	PXHCH2	1,4,8 ON	
	Vigor	1992-1994	PXDP	PXHCH2	1,4,8 ON	
	All Models	2003-2007	Not Compatible			
	MDX	All Years	Not Compatible			
	SLX	All Years	Not Compatible			
NSX	All Years	Not Compatible				

**IMPORTANT ACURA APPLICATION INFORMATION**

PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. Not compatible with factory radios that have an in dash 6 disk cd changer. Not compatible with navigation radios.

\*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings

Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes
Audi	All Models (Except Below)	1998-2004	PXDP	PXHAD1	1,8 ON	Connect at pre-wired 13-pin cable in the left rear trunk.
	All Models (Except Below)	1998-2004	PXDP	PXHAD2 + PXHVW2*	1,8 ON	
	A6	2005-2007	OPIAUDI	Included	n/a	
	A8	2005-2007	OPIAUDI	Included	n/a	
	Q7	2006-2007	OPIAUDI	Included	n/a	

**IMPORTANT AUDI APPLICATION INFORMATION**

PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. Vehicles with Symphony sound systems must use special adapter harness PXHAD2 as well as PXHVW2 and connect at radio.

OPIAUDI: Replaces factory CD Changer. Does not support video iPods.

\*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings

Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes
BMW	3 Series	1996-2005	ISBM71	Included	3,4,8, ON	Not Compatible with DSP radios, Trunk Mounting Location
	5 Series	1996-2005	ISBM71	Included	3,4,8, ON	Not Compatible with DSP radios, Trunk Mounting Location
	7 Series	1999-2001	ISBM71	Included	3,4,8, ON	Not Compatible with DSP radios, Trunk Mounting Location
	Mini	2001-2006	ISBM71	Included	3,4,8, ON	Not Compatible with DSP radios, Trunk Mounting Location
	X5	1999-2005	ISBM71	Included	3,4,8, ON	Not Compatible with DSP radios, Trunk Mounting Location
	Z3/Z5	1998-2003	ISBM71	Included	3,4,8, ON	Not Compatible with DSP radios, Trunk Mounting Location
	Z4	2003-2005	ISBM71	Included	3,4,8, ON	Not Compatible with DSP radios, Trunk Mounting Location

**IMPORTANT BMW APPLICATION INFORMATION**

ISBM71: Not Compatible with Factory Head Units with DSP. "DSP" will be indicated on a radio button. Not compatible with vehicles equipped with iDrive.

\*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings

Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes
Buick	Century	2004-2005	PXDPGMT	PXHGMT	n/a	
	Century	1997-2003	PXDP	PXHGM1 & GMH32T	3,8 ON	Must use GMH32T "T"-harness then plug *PXHGM1 behind radio.
	Enclave	2008	PXDP3	PXH3GM1 or PXH3GM1X	n/a	XM tuner is on the driver side of the dash tucked high up
	Le Sabre	1999-2002	PXDP	PXHGM3	1,3,8 ON	
	Lucerne	2006-2007	PXDP3	PXH3GM1 or PXH3GM1X	n/a	
	Park Ave	1995-2005	PXDP	PXHGM1 & GMH32T	3,8 ON	Must use GMH32T "T"-harness then plug *PXHGM1 behind radio.
	Rainier	2005	PXDP	PXHGM3	1,3,8 ON or \$8	
	Rainier	2005	PXDPGMT	PXHGMT or PXHGTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Regal	1995-2003	PXDP	PXHGM1 & GMH32T	3,8 ON	Must use GMH32T "T"-harness then plug *PXHGM1 behind radio.
	Regal	2004	PXDPGMT	PXHGMT	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Rendezvous	2003-2005	PXDP	PXHGM3	1,3,8 ON or \$8	
	Rendezvous	2003-2006	PXDPGMT	PXHGMT or PXHGTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Riviera	1996-1999	PXDP	PXHGM1 & GMH32T	3,8 ON	Must use GMH32T "T"-harness then plug *PXHGM1 behind radio.
	Roadmaster	1995-1996	PXDP	PXHGM1 & GMH32T	3,8 ON	Must use GMH32T "T"-harness then plug *PXHGM1 behind radio.
	Skylark	1996-1998	PXDP	PXHGM1 & GMH32T	3,8 ON	Must use GMH32T "T"-harness then plug *PXHGM1 behind radio.
	Terraza	2005-2006	PXDPGMT	PXHGMT or PXHGTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Allure	2005	Not Compatible			
	LaCrosse	2005	Not Compatible			

**IMPORTANT BUICK APPLICATION INFORMATION**

PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. GM vehicles 1998 – 2004 not equipped with a factory slave may not be able to support an external device. Therefore the PXDP may not be compatible. If you are an experienced installer, you can retain XM. Please follow this link to the Tech Brief to retain XM: [http://peripheralelectronics.com/web/tech\\_dept.asp](http://peripheralelectronics.com/web/tech_dept.asp). 1995-1999 Radios with built in CD player (Except Corvette) are NOT compatible because they do not have CD changer control functions.

PXDP3: PXH3GM1 is for vehicles without XM, connects to the back of the factory radio. PXH3GM1X harness retains XM and connects to the XM tuner. Non-Navigation radios must have a "CAT" button on the faceplate. Compatible with navigation radios for the applicable vehicles listed above. Compatible with existing factory CD changer. Not Compatible with 2008 GM vehicles.

**PXDPGMT:** Factory radio must be CD changer or XM satellite ready. Factory radio must have a CD player and/or tape player. PXHGMTCD harness is required to retain factory CD Changer. PXHGMT harness is for vehicles without XM installed is installed behind the factory radio. PXHGM2 harness retains XM and is installed at the XM tuner. Rear Seat Entertainment (RSE) will need to be disconnected in order for the PXDPGMT to work properly.

**\*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings**

Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes
Cadillac	Catera	2001	PXDP	PXHGM2	3,8 ON	Behind radio or Trunk Mounting Location
	Deville	1995-2003	PXDP	PXHGM2	3,8 ON or 1,3,8 ON	Behind radio or Trunk Mounting Location
	El Dorado	1995-2002	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location
	Escalade	1999-2002	PXDP	PXHGM1	3,8 ON	
	Escalade	2003-2006	PXDP	PXHGM3	1,3,8 ON or 2,3,8 ON	
	Escalade	2003-2006	PXDPGMT	PXHGMT or PXHGMTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Escalade	2007	PXDP3	PXH3GM1 or PXH3GM1X	n/a	*PLEASE READ IMPORTANT NOTES BELOW
	Seville	1995-2005	PXDP	PXHGM2	3,8 ON	
	XLR	2004-2005	PXDPGMT	PXHGMT or PXHGMTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)

**IMPORTANT CADILLAC APPLICATION INFORMATION**

**PXDP:** Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. GM vehicles 1998 – 2004 not equipped with a factory slave may not be able to support an external device. Therefore the PXDP may not be compatible. If you are an experienced installer, you can retain XM. Please follow this link to the Tech Brief to retain XM: [http://periphalelectronics.com/web/tech\\_dept.asp](http://periphalelectronics.com/web/tech_dept.asp). 1995-1999 Radios with built in CD player (Except Corvette) are NOT compatible because they do not have CD changer control functions.

**PXDP3:** PXH3GM1 is for vehicles without XM, connects to the back of the factory radio. PXH3GM1X harness retains XM and connects to the XM tuner. Non-Navigation radios must have a "CAT" button on the faceplate. Compatible with navigation radios for the applicable vehicles listed above. Compatible with existing factory CD changer. Not Compatible with 2008 GM vehicles. \*In some late production 2007 Escalades GM switched to the 2008 model radio, so the PXDP3 may not be compatible in some 2007 Escalades with the new 2008 model year radio.

**PXDPGMT:** Factory radio must be CD changer or XM satellite ready. Factory radio must have a CD player and/or tape player. PXHGMTCD harness is required to retain factory CD Changer. PXHGMT harness is for vehicles without XM installed is installed behind the factory radio. PXHGM2 harness retains XM and is installed at the XM tuner. Rear Seat Entertainment (RSE) will need to be disconnected in order for the PXDPGMT to work properly.

**\*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings**

Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes
Chevrolet	Astro Van	1996-2005	PXDP	PXHGM1	3,8 ON	
	Avalanche	2002	PXDP	PXHGM1	3,8 ON	
	Avalanche	2003-2006	PXDP	PXHGM3	1,3,8 ON	
	Avalanche	2003-2006	PXDPGMT	PXHGMT or PXHGMTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Avalanche	2007	PXDP3	PXH3GM1 or PXH3GM1X	n/a	
	Blazer	1998-2002	PXDP	PXHGM1	3,8 ON	
	Camaro	1997-2002	PXDP	PXHGM1	3,8 ON	
	Cavalier	1996-1999	PXDP	PXHGM1	3,8 ON	
	Cavalier	2003-2005	PXDPGMT	PXHGMT or PXHGMTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Cavalier	2003-2005	PXDP	PXHGM3	1,3,8 ON or 2,3,8 ON	
	Colorado	2005	PXDP	PXHGM3	1,3,8 ON	
	Colorado	2004-2006	PXDPGMT	PXHGMT or PXHGMTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Corvette	1997-2004	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location
	Corvette	1997-2004	PXDP	PXHGM4	3,8 ON	As a substitute, Can also use PXHGM1 and GMH20T Harnesses
	Express Van	2003-2005	PXDPGMT	PXHGMT or PXHGMTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Impala	1995-1999	PXDP	PXHGM1	3,8 ON	
	Impala	2000-2005	PXDP	PXHGM3	1,3,8 ON	
	Impala	2001-2005	PXDPGMT	PXHGMT or PXHGMTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Impala	2006-2007	PXDP3	PXH3GM1 or PXH3GM1X	n/a	
	Lumina	1996-1999	PXDP	PXHGM1	3,8 ON	
	Malibu	1997-2000	PXDP	PXHGM1	3,8 ON	
	Monte Carlo	1995-1999	PXDP	PXHGM1	3,8 ON	
	Monte Carlo	2000-2005	PXDP	PXHGM3	Config \$7	
	Monte Carlo	2001-2005	PXDPGMT	PXHGMT or PXHGMTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Monte Carlo	2006-2007	PXDP3	PXH3GM1 or PXH3GM1X	n/a	
	Silverado	1996-2002	PXDP	PXHGM1	3,8 ON	
	Silverado	2003-2006	PXDP	PXHGM3	1,3,8 ON	
	Silverado	2003-2006	PXDPGMT	PXHGMT or PXHGMTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Silverado	2007	PXDP3	PXH3GM1 or PXH3GM1X	n/a	Not Compatible with Silverado Classic
	Suburban	1995-2002	PXDP	PXHGM1	3,8 ON	
	Suburban	2003-2006	PXDP	PXHGM3	1,3,8 ON	
	Suburban	2003-2006	PXDPGMT	PXHGMT or PXHGMTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Suburban	2007	PXDP3	PXH3GM1 or PXH3GM1X	n/a	
	Tahoe	1995-2002	PXDP	PXHGM1	3,8 ON	
	Tahoe	2003-2006	PXDP	PXHGM3	1,3,8 ON	
	Tahoe	2003-2006	PXDPGMT	PXHGMT or PXHGMTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Tahoe	2007	PXDP3	PXH3GM1 or PXH3GM1X	n/a	
	Trailblazer	2004-2007	PXDP	PXHGM3	1,3,8 ON or 2,3,8 ON	
	Trailblazer	2002-2007	PXDPGMT	PXHGMT or PXHGMTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Uplander	2005-2006	PXDPGMT	PXHGMT or PXHGMTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Venture	1997-1999	PXDP	PXHGM1	3,8 ON	
	Venture	2004-2005	PXDP	PXHGM3	1,3,8 ON or 2,3,8 ON	
Venture	2002-2006	PXDPGMT	PXHGMTX		PXHGMTCD harness is required to retain factory CD Changer (if equipped)	

**IMPORTANT CHEVROLET APPLICATION INFORMATION**

**PXDP:** Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. GM vehicles 1998 – 2004 not equipped with a factory slave may not be able to support an external device. Therefore the PXDP may not be compatible. If you are an experienced installer, you can retain XM. Please follow this link to the Tech Brief to retain XM: [http://periphalelectronics.com/web/tech\\_dept.asp](http://periphalelectronics.com/web/tech_dept.asp). 1995-1999 Radios with built in CD player (Except Corvette) are NOT compatible because they do not have CD changer control functions.

PXD3: PXH3GM1 is for vehicles without XM, connects to the back of the factory radio. PXH3GM1X harness retains XM and connects to the XM tuner. Non-Navigation radios must have a "CAT" button on the faceplate. Compatible with navigation radios for the applicable vehicles listed above. Compatible with existing factory CD changer. Not Compatible with 2008 GM vehicles.

PXDPGMT: Factory radio must be CD changer or XM satellite ready. Factory radio must have a CD player and/or tape player. PXHGMTCD harness is required to retain factory CD Changer. PXHGMT harness is for vehicles without XM installed is installed behind the factory radio. PXHGMTX harness retains XM and is installed at the XM tuner. Rear Seat Entertainment (RSE) will need to be disconnected in order for the PXDPMGT to work properly.

\*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings

Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes
Chrysler	All Models (Except Below)	2002-2005	PXDP	PXHCH3	4,8 ON	Must be non-CANBUS, if radio is an REF,REC,RAQ, RAK series, vehicles are not compatible
	All Models	1999--2001	PXDP	PXHCH2	4,8 ON	*1999 Radios with rounded corners use PXHCH2
	All Models	1995-1999*	PXDP	PXHCH1	1,4,8 ON	*1999 Radios with square corners use PXHCH1
	300	2005-2007	CHYP	Included	n/a	
	Aspen	2007	CHYP	Included	n/a	
	Pacifica	2006	PXDP	PXHCH3	4,8 ON	
	PT Cruiser	2007	CHYP	Included	n/a	
	Sebring	2006	PXDP	PXHCH3	4,8 ON	
<b>IMPORTANT CHRYSLER APPLICATION INFORMATION</b>						
<p>PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. To determine if your 2002-2005 vehicle is compatible, factory radio must have "Disk ^" on preset 1. Vehicle must be non-CANBUS, if radio is an REF,REC,RAQ, RAK series, vehicles are not compatible. The series is indicated on the front of the radio. 1999 Chrysler vehicles have one of two different style radios. These two radios use different harnesses. The shape of the radio face will determine which harness you will use. If your radio face is SQUARE, you will use the harness part# PXHCH1. If your radio face is OVAL (rounded corners), you will use the harness part# PXHCH2.</p>						
<p>CHYP: Not compatible with REF model factory radios. Model is indicated on the face of the factory radio. Compatible with RAQ, REC, and RAK series factory radios. If the vehicle has a VES (Video Entertainment System), it must be disconnected. The audio from the VES will no longer play through the factory stereo, but the video and wireless headphones will still function normally. VES does NOT operate in R.A.P. mode, the radio will automatically switch from the CHYP to tuner mode during R.A.P. (Retained Accessory Power). Compatible with factory installed satellite.</p>						
*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings						

Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes
Dodge	All Models (Except Below)	2002-2005	PXDP	PXHCH3	4,8 ON	Must be non-CANBUS, if radio is an REF,REC,RAQ, RAK series, vehicles are not compatible
	All Models	1999*-2001	PXDP	PXHCH2	4,8 ON	*1999 Radios with rounded corners use PXHCH2
	All Models	1995-1999*	PXDP	PXHCH1	1,4,8 ON	*1999 Radios with square corners use PXHCH1
	Caliber	2006-2007	CHYP	Included	n/a	
	Charger	2005-2007	CHYP	Included	n/a	
	Dakota	2005-2007	CHYP	Included	n/a	
	Durango	2004-2007	CHYP	Included	n/a	
	Magnum	2005-2007	CHYP	Included	n/a	
Ram	2006-2007	CHYP	Included	n/a		
<b>IMPORTANT DODGE APPLICATION INFORMATION</b>						
<p>PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. To determine if your 2002-2005 vehicle is compatible, factory radio must have "Disk ^" on preset 1. Vehicle must be non-CANBUS, if radio is an REF,REC,RAQ, RAK series, vehicles are not compatible. The series is indicated on the front of the radio. 1999 Chrysler vehicles have one of two different style radios. These two radios use different harnesses. The shape of the radio face will determine which harness you will use. If your radio face is SQUARE, you will use the harness part# PXHCH1. If your radio face is OVAL (rounded corners), you will use the harness part# PXHCH2.</p>						
<p>CHYP: Not compatible with REF model factory radios. Model is indicated on the face of the factory radio. Compatible with RAQ, REC, and RAK series factory radios. If the vehicle has a VES (Video Entertainment System), it must be disconnected. The audio from the VES will no longer play through the factory stereo, but the video and wireless headphones will still function normally. VES does NOT operate in R.A.P. mode, the radio will automatically switch from the CHYP to tuner mode during R.A.P. (Retained Accessory Power). Compatible with factory installed satellite.</p>						
*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings						

Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes
Eagle	All Models	1995-1998	PXDP	PXHCH1	1,4,8 ON	All models must have "Disc ^" printed on Preset Button # 1.
<b>IMPORTANT EAGLE APPLICATION INFORMATION</b>						
<p>PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. If your vehicle is equipped with a factory CD changer, you must disconnect it in order to be able to install the interface. You will lose the use of the factory CD changer to gain use of your iPod.</p>						
*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings						

Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes
Ford	Crown Victoria	1998-2003	PXDP	PXHFD3	2,8 ON	
	Crown Victoria	1995-1997	PXDP	PXHFD2	2,8 ON	
	Crown Victoria	1995-1997	PXDP	PXHFD1	2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk
	Escape	2001-2004	PXDP	PXHFD3	2,8 ON	
	Econoline	1998-2004	PXDP	PXHFD3	2,8 ON	
	Econoline	1997	PXDP	PXHFD2	2,8 ON	
	Escort	1997-2004	PXDP	PXHFD2	2,8 ON	
	Excursion	2000-2004	PXDP	PXHFD3	2,8 ON	
	Expedition	1999-2004	PXDP	PXHFD3	2,8 ON	
	Expedition	1997-1998	PXDP	PXHFD2	2,8 ON	
	Explorer	2005-2007	PXDP2	PXH2FD1	1,2,3 ON	
	Explorer	1998-2004	PXDP	PXHFD3	2,8 ON	
	Explorer	1995-1997	PXDP	PXHFD2	2,8 ON	
	Explorer	1995-1997	PXDP	PXHFD1	2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk
	Freestar	2004	PXDP	PXHFD3	2,8 ON	
	Freestyle	2005-2007	PXDP2	PXH2FD1	1,2,3 ON	
	F-150	2005-2007	PXDP2	PXH2FD1	1,2,3 ON	
	F-250	2007	PXDP2	PXH2FD1	1,2,3 ON	See Important F-250 Compatibility Notes Below
	F-350	2007	PXDP2	PXH2FD1	1,2,3 ON	See Important F-350 Compatibility Notes Below
	F-series Pick Up	1998-2003	PXDP	PXHFD3	2,8 ON	
	F-series Pick Up	1995-1997	PXDP	PXHFD2	2,8 ON	
	Five Hundred	2005-2007	PXDP2	PXH2FD1	1,2,3 ON	
	Focus	2005-2007	Not Compatible	N/A		Not Compatible

Focus	2000-2003	PXDP	PXHFD4	2,8 ON		
Fusion	2006-2007	PXDP2	PXH2FD1	1,2,3 ON		
Mustang	2001-2003	PXDP	PXHFD3	2,8 ON		
Mustang	2005-2007	Not Compatible	N/A		Not Compatible	
Ranger	1998-2004	PXDP	PXHFD3	2,8 ON		
Ranger	1995-1997	PXDP	PXHFD2	2,8 ON		
Sport Trac	2007	PXDP2	PXH2FD1	1,2,3 ON	Sat Tuner located high in the passenger kick panel	
Sport Trac	2000-2004	PXDP	PXHFD3	2,8 ON		
Taurus	1996-2005	PXDP	PXHFD1	2,8 ON	Trunk Mounting Location	
Thunderbird	2000-2004	PXDP	PXHFD3	2,8 ON		
Windstar	1999-2004	PXDP	PXHFD3	2,8 ON		
All	2008	PXDP2	N/A		ALL 2008 Models are NOT Compatible with the PXDP2	
<b>IMPORTANT FORD APPLICATION INFORMATION</b>						
PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. Not compatible with factory radios with built-in 6-disc CD changers. Compatible with factory navigation radios.						
PXDP2: Not compatible with Factory Satellite or Rear Seat Entertainment systems, they must be disconnected for the PXDP2 to operate correctly. Radio must be MP3 compatible, this will be indicated on the face of the radio. Compatible with factory navigation radios. ALL 2008 Models are NOT Compatible with the PXDP2. 250 and F-350: Compatible with factory radios that respond with the text "NO AUX AUDIO" when the Aux button on the factory radio pushed before the interface is installed. If the text displays "NO AUX" the PXDP2 is not compatible.						
*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings						
<b>Make</b>	<b>Model</b>	<b>Year</b>	<b>Part #</b>	<b>Harness</b>	<b>Dip Switch Settings*</b>	<b>Vehicle Specific Notes</b>
<b>GMC</b>	Acadia	2007	PXDP3	PXH3GM1 or PXH3GM1X	n/a	XM tuner is located behind the rear driver's side quarter panel
	Canyon	2004-2006	PXDPGMT	PXHGMT or PXHGTX	3,8 ON	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Envoy	1999-2001	PXDP	PXHGM1	3,8 ON	
	Envoy	2002-2007	PXDPGMT	PXHGMT or PXHGTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Envoy	2004-2007	PXDP	PXHGM3	1,3,8 ON or 2,3,8 ON	
	Denali	1995-2002	PXDP	PXHGM1	3,8 ON	
	Denali	2003-2006	PXDP	PXHGM3	1,3,8 ON	
	Denali	2003-2006	PXDPGMT	PXHGMT or PXHGTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Denali	2007	PXDP3	PXH3GM1 or PXH3GM1X	n/a	
	Jimmy	1998-2002	PXDP	PXHGM1	3,8 ON	
	Sonoma	1998-2002	PXDP	PXHGM1	3,8 ON	
	Safari	1996-2005	PXDP	PXHGM1	3,8 ON	
	Savana	1999-2000	PXDP	PXHGM1	3,8 ON	
	Savana	2003-2006	PXDPGMT	PXHGMT or PXHGTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Sierra	1995-2002	PXDP	PXHGM1	3,8 ON	
	Sierra	2003-2006	PXDP	PXHGM3	1,3,8 ON	
	Sierra	2003-2006	PXDPGMT	PXHGMT or PXHGTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Sierra	2007	PXDP3	PXH3GM1 or PXH3GM1X	n/a	Not Compatible with Sierra Classic
	Sonoma	2003-2004	PXDPGMT	PXHGMT or PXHGTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Suburban	1995-2002	PXDP	PXHGM1	3,8 ON	
Suburban	2003-2006	PXDP	PXHGM3	1,3,8 ON		
Suburban	2003-2006	PXDPGMT	PXHGMT or PXHGTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)	
Suburban	2007	PXDP3	PXH3GM1 or PXH3GM1X	n/a		
Yukon/XL	1995-2002	PXDP	PXHGM1	3,8 ON		
Yukon/XL	2003-2006	PXDP	PXHGM3	1,3,8 ON		
Yukon/XL	2003-2006	PXDPGMT	PXHGMT or PXHGTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)	
Yukon/XL	2007	PXDP3	PXH3GM1 or PXH3GM1X	n/a		
<b>IMPORTANT GMC APPLICATION INFORMATION</b>						
PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. GM vehicles 1998 – 2004 not equipped with a factory slave may not be able to support an external device. Therefore the PXDP may not be compatible. If you are an experienced installer, you can retain XM. Please follow this link to the Tech Brief to retain XM: <a href="http://peripheraelectronics.com/web/tech_dept.asp">http://peripheraelectronics.com/web/tech_dept.asp</a> . 1995-1999 Radios with built in CD player (Except Corvette) are NOT compatible because they do not have CD changer control functions.						
PXDP3: PXH3GM1 is for vehicles without XM, connects to the back of the factory radio. PXH3GM1X harness retains XM and connects to the XM tuner. Non-Navigation radios must have a "CAT" button on the faceplate. Compatible with navigation radios for the applicable vehicles listed above. Compatible with existing factory CD changer. Not Compatible with 2008 GM vehicles.						
PXDPGMT: Factory radio must be CD changer or XM satellite ready. Factory radio must have a CD player and/or tape player. PXHGTXCD harness is required to retain factory CD Changer. PXHGTX harness is for vehicles without XM installed is installed behind the factory radio. PXHGTX harness retains XM and is installed at the XM tuner. Rear Seat Entertainment (RSE) will need to be disconnected in order for the PXDPGMT to work properly.						
*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings						
<b>Make</b>	<b>Model</b>	<b>Year</b>	<b>Part #</b>	<b>Harness</b>	<b>Dip Switch Settings*</b>	<b>Vehicle Specific Notes</b>
<b>Honda</b>	Accord	1998-2002	PXDP	PXHHD1	1,4,8 ON	
	Accord	1992-1997	PXDP	PXHCH2	1,4,8 ON	
	Civic	1998-2004	PXDP	PXHHD1	1,4,8 ON	
	Civic	1992-1997	PXDP	PXHCH2	1,4,8 ON	
	CRV	1998-2004	PXDP	PXHHD1	1,4,8 ON	
	CRV	1997	PXDP	PXHCH2	1,4,8 ON	
	Del Sol	1993-1997	PXDP	PXHCH2	1,4,8 ON	
	Element	2002	PXDP	PXHHD1	1,4,8 ON	
	Insight	2001-2004	PXDP	PXHHD1	1,4,8 ON	
	Odyssey	1995-1997	PXDP	PXHCH2	1,4,8 ON	
	Odyssey	1998-2004	PXDP	PXHHD1	1,4,8 ON	
	Passport	1998-2002	PXDP	PXHHD1	1,2,4,8 ON	
	Prelude	1998-2001	PXDP	PXHHD1	1,4,8 ON	
	Prelude	1992-1997	PXDP	PXHCH2	1,4,8 ON	
	S2000	2000-2003	PXDP	PXHHD1	1,4,8 ON	

	All Models	2005-2007		Not Compatible		
	Accord	2003-2004		Not Compatible		
	Pilot	All Years		Not Compatible		
	Ridgeline	All Years		Not Compatible		
	S2000	2004		Not Compatible		
<b>IMPORTANT HONDA APPLICATION INFORMATION</b>						
PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. Not compatible with factory radios that have an in dash 6 disk cd changer. Not compatible with navigation radios.						
*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings						
<b>Make</b>	<b>Model</b>	<b>Year</b>	<b>Part #</b>	<b>Harness</b>	<b>Dip Switch Settings*</b>	<b>Vehicle Specific Notes</b>
<b>Hummer</b>	H2	2003-2006	PXDP	PXHGM3	1,3,8 ON or 2,3,8 ON	*2003-2005 Must disable factory XM Tuner if equipped
	H2	2003-2007	PXDPGMT	PXHGMT or PXHGMTX	n/a	PXHGMTCD harness is also required to retain factory CD Changer (if equipped)
	H3	2005	PXDP	PXHGM3	1,3,8 ON or 2,3,8 ON	
<b>IMPORTANT HUMMER APPLICATION INFORMATION</b>						
PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function.						
PXDPGMT: Factory radio must be CD changer or XM satellite ready. Factory radio must have a CD player and/or tape player. PXHGMTCD harness is required to retain factory CD Changer. PXHGMT harness is for vehicles without XM installed is installed behind the factory radio. PXHGMTX harness retains XM and is installed at the XM tuner. Rear Seat Entertainment (RSE) will need to be disconnected in order for the PXDPGMT to work properly.						
*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings						
<b>Make</b>	<b>Model</b>	<b>Year</b>	<b>Part #</b>	<b>Harness</b>	<b>Dip Switch Settings*</b>	<b>Vehicle Specific Notes</b>
<b>Isuzu</b>	Amigo	1998-2002	PXDP	PXHTY3	1,2,4,8 ON	
	Rodeo	1998-2002	PXDP	PXHTY3	1,2,4,8 ON	
	Trooper	1998-2002	PXDP	PXHTY3	1,2,4,8 ON	
<b>IMPORTANT ISUZU APPLICATION INFORMATION</b>						
PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function.						
*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings						
<b>Make</b>	<b>Model</b>	<b>Year</b>	<b>Part #</b>	<b>Harness</b>	<b>Dip Switch Settings*</b>	<b>Vehicle Specific Notes</b>
<b>Jaguar</b>	S-Type	2000-2002	PXDP	PXHFD4	2,8 ON	
	<b>IMPORTANT JAGUAR APPLICATION INFORMATION</b>					
PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function.						
*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings						
<b>Make</b>	<b>Model</b>	<b>Year</b>	<b>Part #</b>	<b>Harness</b>	<b>Dip Switch Settings*</b>	<b>Vehicle Specific Notes</b>
<b>Jeep</b>	All Models	2002-2005	PXDP	PXHCH3	4,8 ON	Must be non-CANBUS, if radio is an REF,REC,RAQ, RAK series, vehicles are not compatible
	All Models	1999*-2001	PXDP	PXHCH2	4,8 ON	*1999 Radios with rounded corners use PXHCH2
	All Models	1995-1999*	PXDP	PXHCH1	1,4,8 ON	*1999 Radios with square corners use PXHCH1
	Grand Cherokee	2005-2007	CHYP	Included	n/a	
	Commander	2005-2007	CHYP	Included	n/a	
	Compass	2007	CHYP	Included	n/a	
	Patriot	2007	CHYP	Included	n/a	
	<b>IMPORTANT JEEP APPLICATION INFORMATION</b>					
PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. To determine if your 2002-2005 vehicle is compatible, factory radio must have "Disk ^" on preset 1. Vehicle must be non-CANBUS, if radio is an REF,REC,RAQ, RAK series, vehicles are not compatible. The series is indicated on the front of the radio. 1999 Chrysler vehicles have one of two different style radios. These two radios use different harnesses. The shape of the radio face will determine which harness you will use. If your radio face is SQUARE, you will use the harness part# PXHCH1. If your radio face is OVAL (rounded corners), you will use the harness part# PXHCH2.						
CHYP: Not compatible with REF model factory radios. Model is indicated on the face of the factory radio. Compatible with RAQ, REC, and RAK series factory radios. If the vehicle has a VES (Video Entertainment System), it must be disconnected. The audio from the VES will no longer play through the factory stereo, but the video and wireless headphones will still function normally. VES does NOT operate in R.A.P. mode, the radio will automatically switch from the CHYP to tuner mode during R.A.P. (Retained Accessory Power). Compatible with factory installed satellite.						
*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings						
<b>Make</b>	<b>Model</b>	<b>Year</b>	<b>Part #</b>	<b>Harness</b>	<b>Dip Switch Settings*</b>	<b>Vehicle Specific Notes</b>
<b>Lexus</b>	ES330	2005	PXDP2	PXH2TY1	2,4 ON	
	GS300	2006	PXDP2	PXH2TY1	2,4 ON	
<b>IMPORTANT LEXUS APPLICATION INFORMATION</b>						
PXDP2: Radio must have a button labeled "SAT". Fully compatible with factory installed Lexus Navigation Systems. Not compatible with factory satellite. If satellite is installed, it must be disconnected. Not compatible with Hybrid vehicles.						
*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings						
<b>Make</b>	<b>Model</b>	<b>Year</b>	<b>Part #</b>	<b>Harness</b>	<b>Dip Switch Settings*</b>	<b>Vehicle Specific Notes</b>
<b>Lincoln</b>	Aviator	2002-2003	PXDP	PXHFD3	2,8 ON	
	Continental	1998-2004	PXDP	PXHFD3	2,8 ON	
	Continental	1995-1997	PXDP	PXHFD2	2,8 ON	
	Continental*	1995-1997	PXDP	PXHFD1	2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk
	LS	2000-2003	PXDP	PXHFD3	2,8 ON	
	Mark VIII	1995-1998	PXDP	PXHFD2	2,8 ON	
	Mark LT	2005-2006	PXDP2	PXH2FD1	1,2,3 ON	
	Navigator	1999-2003	PXDP	PXHFD3	2,8 ON	
	Navigator	1997-1998	PXDP	PXHFD2	2,8 ON	
	Town Car	1998-2003	PXDP	PXHFD3	2,8 ON	
	Town Car	1995-1997	PXDP	PXHFD2	2,8 ON	
	Town Car*	1995-1997	PXDP	PXHFD1	2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk
All	2008	PXDP2	N/A		ALL 2008 Models are NOT Compatible with the PXDP2	
<b>IMPORTANT LINCOLN APPLICATION INFORMATION</b>						
PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. Not compatible with factory radios with built-in 6-disc CD changers. Compatible with factory navigation radios.						
PXDP2: Not compatible with Factory Satellite or Rear Seat Entertainment systems, they must be disconnected for the PXDP2 to operate correctly. Radio must be MP3 compatible, this will be indicated on the face of the radio. Compatible with factory navigation radios. ALL 2008 Models are NOT Compatible with the PXDP2						

*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings						
Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes
Mazda	B-series Truck	1998-2001	PXDP	PXHFD3	2,8 ON	
	B-series Truck	1997	PXDP	PXHFD2	2,8 ON	
	<b>IMPORTANT MAZDA APPLICATION INFORMATION</b>					
	PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function.					
*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings						
Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes
Mercedes Benz	C	2005-2007	Opi-M	Included	n/a	
	CL	2004-2007	Opi-M	Included	n/a	
	CLK	2004-2007	Opi-M	Included	n/a	
	CLS	2005-2007	Opi-M	Included	n/a	
	E	2003-2007	Opi-M	Included	n/a	
	GL	2007	Opi-M	Included	n/a	
	Maybach	2004-2007	Opi-M	Included	n/a	
	ML	2006-2007	Opi-M	Included	n/a	
	R	2006-2007	Opi-M	Included	n/a	
	SL	2006-2007	Opi-M	Included	n/a	
	SLK	2005-2007	Opi-M	Included	n/a	
	<b>IMPORTANT MERCURY APPLICATION INFORMATION</b>					
Opi-M: Must disconnect factory CD changer. Must be a Navigation Radio						
Opi-M: Must be a MOST Databus vehicle						
Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes
Mercury	Cougar	1999-2004	PXDP	PXHFD4	1,2,8 ON	
	Grand Marquis	1998-2003	PXDP	PXHFD3	2,8 ON	
	Grand Marquis	1995-1997	PXDP	PXHFD2	2,8 ON	
	Grand Marquis	1995-1997	PXDP	PXHFD1	2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk
	Montego	2005-2006	PXDP2	PXH2FD1	1,2,3 ON	
	Mountaineer	1998-2004	PXDP	PXHFD3	2,8 ON	
	Mountaineer	1995-1997	PXDP	PXHFD2	2,8 ON	
	Mountaineer	1995-1997	PXDP	PXHFD1	2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk
	Sable	1996-2005	PXDP	PXHFD1	2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk
	Tracer	1995-2004	PXDP	PXHFD1	2,8 ON	*If equipped with JBL, use PXHFD1 at Rear Control Unit in trunk
	Villager	1999-2002	PXDP	PXHFD3	2,8 ON	
	All	2008	PXDP2	N/A		ALL 2008 Models are NOT Compatible with the PXDP2
<b>IMPORTANT MERCURY APPLICATION INFORMATION</b>						
PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. Not compatible with factory radios with built-in 6-disc CD changers. Compatible with factory navigation radios.						
PXDP2: Not compatible with Factory Satellite or Rear Seat Entertainment systems, they must be disconnected for the PXDP2 to operate correctly. Radio must be MP3 compatible, this will be indicated on the face of the radio. Compatible with factory navigation radios. ALL 2008 Models are NOT Compatible with the PXDP2						
*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings						
Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes
Nissan	Quest	1999-2002	PXDP	PXHFD3	2,8 ON	
	<b>IMPORTANT NISSAN APPLICATION INFORMATION</b>					
PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function.						
*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings						
Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes
Oldsmobile	Achieva	1996-1998	PXDP	PXHGM3	1,3,8 ON	Trunk/CD Changer Mounting Location
	Alero	2003-2004	PXDP	PXHGM3	2,3,8 ON	
	Alero	2001-2004	PXDPGMT	PXHGMT or PXHGMTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Alero	1999-2000	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location
	Aurora	2001-2004	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location
	Aurora	1995-1999	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location
	Bravada	2004	PXDP	PXHGM3	1,3,8 ON or 2,3,8 ON	
	Bravada	2002-2004	PXDPGMT	PXHGMT or PXHGMTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Bravada	1997-2001	PXDP	PXHGM1	3,8 ON	
	Cutlass	1997-1999	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location
	Cutlass Supreme	1995-1997	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location
	Eighty-Eight	1996-1999	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location
	Intrigue	1998-2001	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location
	LSS	1996-1999	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location
	Regency	1997-1998	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location
	Silhouette	2004	PXDP	PXHGM3	2,3,8 ON	
	Silhouette	2003-2004	PXDPGMT	PXHGMT	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)
	Silhouette	1996-1999	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location
<b>IMPORTANT OLDSMOBILE APPLICATION INFORMATION</b>						
PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. GM vehicles 1998 – 2004 not equipped with a factory slave may not be able to support an external device. Therefore the PXDP may not be compatible. If you are an experienced installer, you can retain XM. Please follow this link to the Tech Brief to retain XM: <a href="http://peripheraelectronics.com/web/tech_dept.asp">http://peripheraelectronics.com/web/tech_dept.asp</a> . 1995-1999 Radios with built in CD player (Except Corvette) are NOT compatible because they do not have CD changer control functions.						
PXDPGMT: Factory radio must be CD changer or XM satellite ready. Factory radio must have a CD player and/or tape player. PXHGMTCD harness is required to retain factory CD Changer. PXHGMT harness is for vehicles without XM installed is installed behind the factory radio. PXHGMTX harness retains XM and is installed at the XM tuner. Rear Seat Entertainment (RSE) will need to be disconnected in order for the PXDPGMT to work properly.						
*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings						

Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes	
Plymouth	All Models	1995-2000	PXDP	PXHCH1	1,4,8 ON	All models must have "Disc ^" printed on Preset Button # 1.	
	Neon	2002-2004	PXDP	PXHGM3	1,4,8 ON		
	<b>IMPORTANT PLYMOUTH APPLICATION INFORMATION</b>						
	PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function.						
*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings							
Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes	
Pontiac	Aztec	2003-2005	PXDP	PXHGM3	1,3,8 ON or 2,3,8 ON		
	Aztec	2001-2006	PXDPGMT	PXHGMT or PXHGMTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)	
	Bonneville	2000-2005	PXDP	PXHGM2	3,8 ON	Trunk Mounting Location	
	Bonneville	1996-1999	PXDP	PXHGM1	3,8 ON		
	Firebird / Trans Am	1996-2002	PXDP	PXHGM1	3,8 ON		
	Grand AM	2003-2005	PXDP	PXHGM3	1,3,8 ON or 2,3,8 ON		
	Grand AM	2000-2006	PXDPGMT	PXHGMT or PXHGMTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)	
	Grand AM	1996-2000	PXDP	PXHGM1	3,8 ON		
	Montana	2004-2005	PXDP	PXHGM3	1,3,8 ON or 2,3,8 ON		
	Montana	2001-2005	PXDPGMT	PXHGMT or PXHGMTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)	
	Montana	1999-2000	PXDP	PXHGM1	3,8 ON		
	Sunfire	2003-2005	PXDP	PXHGM3	1,3,8 ON		
	Sunfire	2000-2005	PXDPGMT	PXHGMT or PXHGMTX	n/a	PXHGMTCD harness is required to retain factory CD Changer (if equipped)	
	Sunfire	1996-1999	PXDP	PXHGM1	3,8 ON		
	TransSport	1996-1998	PXDP	PXHGM1	3,8 ON		
	Vibe	2004-2005	PXDP	PXHGM3	1,3,8 ON or 2,3,8 ON		
	G6	2005	Not Compatible				
	Grand Prix	2004-2007	Not Compatible				
<b>IMPORTANT PONTIAC APPLICATION INFORMATION</b>							
PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. GM vehicles 1998 – 2004 not equipped with a factory slave may not be able to support an external device. Therefore the PXDP may not be compatible. If you are an experienced installer, you can retain XM. Please follow this link to the Tech Brief to retain XM: <a href="http://periphalelectronics.com/web/tech_dept.asp">http://periphalelectronics.com/web/tech_dept.asp</a> . 1995-1999 Radios with built in CD player (Except Corvette) are NOT compatible because they do not have CD changer control functions.							
PXDPGMT: Factory radio must be CD changer or XM satellite ready. Factory radio must have a CD player and/or tape player. PXHGMTCD harness is required to retain factory CD Changer. PXHGMT harness is for vehicles without XM installed is installed behind the factory radio. PXHGMTX harness retains XM and is installed at the XM tuner. Rear Seat Entertainment (RSE) will need to be disconnected in order for the PXDPGMT to work properly.							
*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings							
Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes	
Porsche	All Models with Navigation	2005-2007	OPIP		n/a	Must be a MOST Databus vehicle	
	All Models with Navigation	2004	OPIP04		n/a	Must be a MOST Databus vehicle	
	<b>IMPORTANT PONTIAC APPLICATION INFORMATION</b>						
OPIP/OPIP04: Must disconnect factory CD changer. Must be a Navigation Radio							
Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes	
Saturn	All Models	1995-1999	PXDP	PXHGM1	3,8 ON		
	Outlook	2007	PXD3	PXH3GM1 or PXH3GM1X	n/a	XM tuner is on the driver side of the dash tucked high up	
	<b>IMPORTANT SATURN APPLICATION INFORMATION</b>						
	PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function.						
PXD3: PXH3GM1 is for vehicles without XM, connects to the back of the factory radio. PXH3GM1X harness retains XM and connects to the XM tuner. Non-Navigation radios must have a "CAT" button on the faceplate. Compatible with navigation radios for the applicable vehicles listed above. Compatible with existing factory CD changer. Not Compatible with 2008 GM vehicles.							
*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings							
Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes	
Scion	tC	2003-2007	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness	
	xA	2003-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness	
	xB	2003-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness	
	<b>IMPORTANT SCION APPLICATION INFORMATION</b>						
PXDP: Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function.							
*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings							
Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes	
Suzuki	XL-7	2007	PXD3	PXH3GM1 or PXH3GM1X	n/a		
	<b>IMPORTANT SCION APPLICATION INFORMATION</b>						
PXD3: Non-Navigation radios must have a "CAT" button on the faceplate. Compatible with all navigation radios. Compatible with existing factory CD changer. PXH3GM1 is for vehicles without XM, connects to the back of the factory radio. PXH3GM1X harness retains XM, connects to the XM tuner.							
Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes	
Toyota	4Runner	1998-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness	
	4Runner	2005-2007	PXD2	PXH2TY1	2,4 ON		
	4Runner	2006-2007	PXDP	PXHTY3 or PXH2TY1	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness	
	Avalon	1998-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness	
	Avalon	2005-2007	PXD2	PXH2TY1	2,4 ON		
	Avalon	2006-2007	PXDP	PXHTY3 or PXH2TY1	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness	
	Camry	1998-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness	
	Camry	2005-2007	PXD2	PXH2TY1	2,4 ON		
	Camry	2006-2007	PXDP	PXHTY3 or PXH2TY1	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness	
	Celica	1998-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness	
	Corolla	1998-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness	
	Corolla	2006-2007	PXDP	PXHTY3 or PXH2TY1	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness	
	Echo	2000-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness	
	FJ Cruiser	2007	PXD2	PXH2TY1	2,4 ON		

Highlander	2001-2004	PXDP	PXH2TY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness
Highlander	2005-2007	PXDP2	PXH2TY1	2,4 ON	
Highlander	2006-2007	PXDP	PXHTY3 or PXH2TY1	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness
Land Cruiser	1998-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness
Land Cruiser	2005-2007	PXDP2	PXH2TY1	2,4 ON	
Land Cruiser	2006-2007	PXDP	PXHTY3 or PXH2TY1	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness
Matrix	2003-2004	PXDP	PXHGM3	1,3,8 ON	
Matrix	2005-2007	PXDP2	PXH2TY1	2,4 ON	
Matrix	2006-2007	PXDP	PXHTY3 or PXH2TY1	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness
MR2	2000-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness
RAV4	1998-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness
RAV4	2005-2007	PXDP2	PXH2TY1	2,4 ON	
Sequoia	2001-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness
Sequoia	2005-2007	PXDP2	PXH2TY1	2,4 ON	
Sequoia	2006-2007	PXDP	PXHTY3 or PXH2TY1	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness
Sienna	1998-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness
Sienna	2005-2007	PXDP2	PXH2TY1	2,4 ON	
Sienna	2006-2007	PXDP	PXHTY3 or PXH2TY1	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness
Solara	1999-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness
Solara	2005-2007	PXDP2	PXH2TY1	2,4 ON	
Solara	2006-2007	PXDP	PXHTY3 or PXH2TY1	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness
Supra	1998	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness
T100	1998	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness
Tacoma	1998-2005	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness
Tacoma	2005-2007	PXDP2	PXH2TY1	2,4 ON	
Tacoma	2006-2007	PXDP	PXHTY3 or PXH2TY1	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness
Tercel	1998	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness
Tundra	2000-2007	PXDP	PXHTY3	1,2,4,8 ON	When using the PXHTY3 the green wires must be cut on the PXHTY3 harness
Tundra	2007	PXDP2	PXH2TY1	2,4 ON	
Yaris	2005-2007	PXDP2	PXH2TY1	2,4 ON	
Prius	All Years	Not Compatible			
Highlander	2008	Not Compatible			

**IMPORTANT TOYOTA APPLICATION INFORMATION**

**PXDP:** Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. When using the PXHTY3 with 2006-2007 vehicles the green wires must be cut on the PXHTY3 harness. Fully compatible with factory installed Toyota Navigation Systems. Not compatible with Hybrid vehicles.

**PXDP2:** Radio must have a button labeled "SAT". Not compatible with factory satellite. If satellite is installed, it must be disconnected. Fully compatible with factory installed Toyota Navigation Systems. Not compatible with Hybrid vehicles.

\*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings

Make	Model	Year	Part #	Harness	Dip Switch Settings*	Vehicle Specific Notes
Volkswagen	All Models (Except Below)	1998-2006	PXDP	PXHVV1	1,8 ON	Trunk Mounting Location
	All Models	1998-2006	PXDP	PXHVV2	1,8 ON	For use with Single DIN radios
	All Models	2003-2006	PXDP	PXHVV3	1,8 ON	For use with Double DIN radios

**IMPORTANT VOLKSWAGEN APPLICATION INFORMATION**

**PXDP:** Not compatible with any factory external audio source such as: XM tuner, CD changer, or Cassette player. These devices must be disconnected during the installation and will no longer function. Not compatible with vehicles equipped with a factory Navigation system. When possible, we recommend using the PXHVW2 or PXHVW3 harness and install the PXDP behind the radio. This will avoid the possibility of inherent noise problems with the factory VW CD changer cable that is found in some vehicles. Double DIN (4" Tall) VW radios require the PXHVW3 to connect behind the radio.

**PXHVV3:** When using the PXHVW3 harness, connect the loose black lead to suitable chassis ground. If equipped with factory satellite, remove the blue OEM sub harness from the main OEM harness to plug in the PXHVW3 harness.

\*Dip Switch Settings: Please See Product Instructions for Dip Switch Configuration Settings

Revision History			
Date	Vehicle	Year	Notes
9/21/2007	Pontiac Grand Prix	2004-2007	PXDPGMT Removed
8/31/2007	Ford Focus	2005-2007	PXDP2 Removed
8/24/2007	Chrysler Pacifica	2006	PXDP Added
8/24/2007	PT Cruiser	2007	CHYP Added
8/24/2007	Ford/Lincoln/Mercury	2008	PXDP2 NOT Compatible
8/3/2007	Toyota Corolla	2005-2007	PXDP2 Removed
7/23/2007	GMC Envoy	2007	PXDP, PXDPGMT Added
7/31/2007	Toyota Tundra	2006-2007	PXDP Added
7/23/2007	Scion TC	2006-2007	PXDP Added
7/23/2007	Audio A6	2005-2007	OPIAUDI Added
7/23/2007	Audi A8	2005-2007	OPIAUDI Added
7/23/2007	Audi Q7	2006-2007	OPIAUDI Added
7/18/2007	Saturn Outlook	2007	PXDP3 Added
7/18/2007	Buick Enclave	2008	PXDP3 Added
7/15/2007	Cadillac Catera	2001	PXDP Added
7/10/2007	Suzuki XL-7	2007	PXDP3 Added
7/10/2007	Pontiac Grand Prix	2006-2007	PXDPGMT Added to Guide
6/29/2007	GMC Acadia	2007	PXDP3 Added
5/22/2007	Lexus ES330	2005	PXDP2 Added
5/22/2007	Porsche with Nav	2004	OPIP04 Added
5/15/2007	Trailblazer	2007	PXDP Added